Wednesday, 6/28/2006 4:18:34 PM Date: Kim Johnston User: **Process Sheet** : STEP SPACER Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 27756C **Estimate Number** : 10354 M4: : D2322 Part Number P.O. Number : D2322 REV C : 6/28/2006 S.O. No. : 211 **Drawing Number** This Issue Prsht Rev. **Project Number** : N/A : NIA : SMALL /MED FAB First Issue Type **Drawing Revision** : 25395C **Previous Run** Material : 7/12/2006 Each **Due Date** Qty: 20 Um: Written By Checked & Approved By Comment **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: 1.0 M2024T3S040 2024-T3 .040 sheet Comment: Qty.: 4.2630 sf(s) 0.2132 sf(s)/Unit Total: Material: 2024-T3 sheet (QQ-A-250/4) 0.040" Thick (M2024T3S.040) Identify as D2322 Batch: <u>MI9295</u> SHEAR 2.0 SHEAR Comment: SHEAF Ø.010" (grain along 4.500") HAAS CNC VERTICAL MACHINING #1 Comment: HAAS Machine as per folio D2322, was stacked 15 4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 5.0 SECOND CHECK Comment: SECOND CHECK

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
			j	٠				
							1	

NCR:	1770	SCC. WI	ORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC	Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Design Mgr	Approval QC Inspector
06:07:11	3.	hole of 3 piece were to mater Jet. open the wrong The wrong The wrong The water Jet. open to Error 2 ports Scrap. W. J. danney	Bur	scrap and datroy	5AD 06.07:11	06-57-13	De sur	0.03.11
060713	3	2 parts scrap. W.J. danny	Orgers	Scripp is less troy.	M/ 05 07 13	01-0713	Grans	N-02-13
0407/19	7	of tolerance	Mys	Scrap + destroy	5B 06/07/19	06.02.10	A VIII	man h

Part No: 02322

PAR #: What Fault Category: Pod machines Prince: (Pes) No DQA: N/C Closed:

NOTE: Date & initial all entries

Date: Wednesday, 6/28/2006 4:18:34 PM User: Kim Johnston **Process Sheet Drawing Name: STEP SPACER** Customer: CU-DAR001 Dart Helicopters Services Job Number: 27756C Part Number: D2322 Job Number: Seq. #: Machine Or Operation: Description: SMALL & MEDIUM FAB RESOURCE 1 6.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Deburr BRAKE NC NC BRAKE 7.0 Comment: NC BRAKE Form as per Dwg D2322 8.0 INSPECT WORK TO CURRENT STE QC5 Comment: INSPECT WORK TO CURRENT STEP 9.0 HAND FINISHING1 \ HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 10.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 06507:31 12.0 DC DOCUMENT CONTROL Comment: DOCUMENT CONTROL 08/80/20 Inspection Level 21 Job Completion CL06108101

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
					· · · · · · · · · · · · · · · · · · ·				
NCR:		W	ORK ORDER NON-CONF	ORMANCE (NCF	₹)				
DATE	eten.	Description of NC	Corrective Action	Section B	Verific	cation	Approval	Approval	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Varification		Approval			
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector			
	·										
	-										
4											

Part No:	PAR #:	Fault Category:	_ NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	I/C CI	osed:	Date:

DART AEROSPACE LTD	Work Order:	27756C
Description: Step Spacer	Part Number:	D2322
Inspection Dwg: D2322 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

x	First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.250	+/-0.005	0,251	/		Vern	
4.178	+/-0.005	94,183			Vern	
4.428	+/-0.010	4.425	V		Man	
0.250	+/-0.005	0.252			Vern	
6.520	+/-0.010				Vern	
Ø0.128	+/-0.010 +0.005/-0.000 ≥	50,128	سسن		Very	
R0.125	+/-0.010	RO. 125			Vern Vern Vern Vern	Tause
					. 1	
					#	

Measured by: SAD	Audited by:	Prototype Approval:	N/A
Date: 06:07:11	Date: 06.01. U	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α	04.10.12	New Issue	P/O D2582	KJ/JLM O	



Copyright 1994 by DART AEROSPACE LTD

Tuesday, 04/07/2006 9:10:16 AM

User:

Linda Lacelle

Process Sheet

Customer

This Issue

Prsht Rev.

First Issue

Previous Run

: CU-DAR001 Dart Helicopters Services

Job Number : 27756C **Estimate Number** : 10354

P.O. Number

: NIA

: 28/06/2006

: 25395C

: NC

: 04/07/2006

S.O. No. : NA

: SMALL /MED FAB

JLM

Part Number Drawing Number

Project Number **Drawing Revision**

Drawing Name

Material

All: : 12/07/2006 **Due Date**

: STEP SPACER

D2322 REV C

: D2322

: N/A

; C

Qty:

20 Um:

Each

Written By

Checked & Approved By

Comment

: Est Rev:A

New Issue 05-11-07

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: 2024-T3 .040 sheet

1.0

M2024T3S040



Comment: Qty.: 0.2132 sf(s)/Unit Total: 4.2630 sf(s) Material: 2024-T3 sheet (QQ-A-250/4) 0.040" Thick

> (M2024T3S.040) Identify as D2322

2.0

FLOW WATER JET



Comment: FLOW WATER JET

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK

5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr

Page 1

Date: User: Tuesday, 04/07/2006 9:10:16 AM

· Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP SPACER

Description:

Job Number: 27756C

Part Number: D2322

Job Number:



Seq. #:

Machine Or Operation:

6.0

BRAKE NC

NC BRAKE

Comment: NC BRAKE

Form as per Dwg D2322

7.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

10.0

PACKAGING 1

Location:

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

11.0 DC DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion

